

lassified in Part - Sanitized Copy Ap	proved for Release 2011/11/09 : CIA-RDP89-00121R000	100150001-5
•	SECRET	
		25 <b>X</b> 1
(c) NATIONA	AL PHOTOGRAPHIC INTERPRETATION CENTER	
n 11	Attachment to Z-10	0094/82
Page 1 of 1 Copy		C/PEG (1/82)
. ,	IMPROVED REPAIR CAPABILITY	:
	KA NAVAL BASE AND SHIPYARD, USSR	25 <b>X</b> 1
		23/1
1. (S/D) SIGNIFICANC APPARENTLY ARE OP	E: IMPROVED REPAIR FACILITIES AT PETRO ERATIONAL.	VKA
2. (S/D) REMARKS: A	LARGE FLOATING DRY DOCK HAS BEEN MOVED SE AND SHIPYARD SINCE	TO WHERE 25X1
IT IS ALIGNED WIT	, ,	DOCK
FACILITY (	A COLLOCATED FACILITY, BY THE SHIPYARD WILL NOW HAVE A MUCH IMPRO	25X1
CAPABILITY FOR EX	TENDED OUT-OF-WATER REPAIR OF SUBMARINE	
NUCLEAR-POWERED B	ENGTH AND TONNAGE, THAN Y-CLASS SALLISTIC MISSILE SUBMARINES. WITHOUT T	
REPAIRWAYS AND TH	S SUBMARINES WHICH COULD BE MOVED TO THE REPAIR HALLS WAS CONSTRAINED BY THE L	ENGTH
	THE SHIPLIFING BASIN.	25 <b>X</b> 1
	OORDINATES 43-07-19N 132-20-24E	
COMMENTS AND QUER DIRECTED TO THE N	RIES REGARDING THIS BRIEFING BOARD MAY EN PRIC/PEG OPERATIONS OFFICER.	3E
These notes have been prepared for brid	efing purposes only and should not be used for detailed ana-	25X1
Livrical work. Their use should be restrict	ted to the particular briefing board(s) they were prepared for e reporting period as indicated by the date of issue.	
WARNING NOTICE		
Intelligence Sources and Methods Involved	SECRET	

Declassified in Part - Sanitized Copy Approved for Release 2011/11/09 : CIA-RDP89-00121R000100150001-5

Declassified in Part - Sanitized Copy Approved for Release 2011/11/09 : CIA-RDP89-00121R000100150001-5

